

## Onderhoud BOOOM-HELIX-BEEHIVE Aluminium

*Wij adviseren de Helix zo min mogelijk te reinigen, mocht u de Helix toch willen reinigen doe dit dan met beleid en volgens ons protocol. Het snel verwijderen van vetvlekken kan het best door voorzichtig te poetsen met een stuk wc papier.*

*Voor het verwijderen van (vet)vlekken en/of vingerafdrukken plaatst u de lamp op een tafel bedekt met een kleed (voor het voorkomen van krassen). Als poetsmiddel gebruikt u een RVS cleaner op basis van olie. Met een droge doek en zeer weinig olie kan de lamp met een roterende beweging licht opgepoetst worden. Een dun film laagje van de olie blijft achter op het oppervlak waardoor vingerafdrukken en vetvlekken niet meer zichtbaar zullen zijn. Gebruik van stoffen handschoenen (voor het voorkomen van vingerafdrukken) is aanbevolen. Na afloop kunt u met een schone, droge doek de lamp verder oppoetsen.*

*Behandel de lamp niet met water of schoonmaakmiddel dit kan de lamp aantasten.*

## Onderhoud BOOOM-HELIX-BEEHIVE Messing/Koper

*Wij adviseren de Helix zo min mogelijk te reinigen, mocht u de Helix toch willen reinigen doe dit dan met beleid en volgens ons protocol.*

*Voor het verwijderen van (vet)vlekken en/of vingerafdrukken plaatst u de lamp op een tafel bedekt met een kleed (voor het voorkomen van krassen). Met de schuurkant van een droge schuurspons (afwasspons) poetst u de lamp lichtjes met een roterende beweging schoon. Gebruik van stoffen handschoenen (voor het voorkomen van vingerafdrukken) is aanbevolen. Na afloop kunt u met een schone, droge doek de lamp licht oppoetsen.*

*Behandel de lamp niet met water of schoonmaakmiddel dit kan de lamp aantasten. De messing versie van de Helix zal na verloop van tijd verkleuren. Een diep bruine gloed ontstaat door oxidatie (patina).*



by  
**Marc de Groot**



## Maintenance BOOOM-HELIX-BEEHIVE Aluminium

*We recommend to clean the Helix as little as possible. If you really want to clean the Helix please proceed according to our protocol. For rapid removal of grease it's best to brush gently with a piece of toilet paper instead of cleaning the Helix thoroughly.*

*To remove (fat)stains and/or fingerprints, place the lightning fixture on a table covered with a cloth (to prevent scratches). For best results you can use a stainless steel polish cleaner on oil base. With a dry cloth and very little oil the lamp can be polished in a rotating motion. A thin layer of oil remains on the surface, fingerprints and grease stains will no longer be visible. Use of gloves (to prevent getting fingerprints on the surface) is recommended. Afterwards you can continue polishing the lamp with a clean, dry cloth.*

**Do not treat the lamp with water or detergent because it may damage the Hegiulix.**

## Maintenance BOOOM-HELIX-BEEHIVE Brass/Copper

*We recommend to clean the Helix as little as possible. If you really want to clean the Helix please proceed according to our protocol.*

*To remove (fat)stains and/or fingerprints, place the lamp on a table covered with a cloth (to prevent scratches). With the abrasive side of a dry abrasive sponge (washing sponge) you brush the lamp with a rotating motion to clean it. Use of gloves (to prevent getting fingerprints on the surface) is recommended. Afterwards you can continue polishing the lamp with a clean, dry cloth.*

**Do not treat the lamp with water or detergent because it may damage the Helix. The brass version of the Helix will discolour over time. A deep brown glow caused by oxidation (patina) will appear.**

